
From: Michael A Glagola (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MIC0210]
Sent: 3/12/2016 11:07:16 AM
To: Christine Harris (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Christ3]
Subject: Re: Problem with Flow able fill in S107 needs to be resolved

Yes.

Sent from my iPhone

On Mar 12, 2016, at 11:06 AM, Christine Harris (Generation - 34) <christine.harris@dom.com> wrote:
Thanks. This is the toe drain- correct?

Sent from my iPhone

On Mar 12, 2016, at 10:10 AM, Michael A Glagola (Generation - 34) <michael.a.glagola@dom.com> wrote:
Yes. They are still making changes to the concrete mix adding a vent to the pipe to ensure flow. Kevin, Glover, GAI and PGE have it under control.

Mike

Sent from my iPhone

On Mar 12, 2016, at 8:17 AM, Christine Harris (Generation - 34) <christine.harris@dom.com> wrote:
Was this resolved?

Sent from my iPhone

Begin forwarded message:

From: "David R Payne (Generation - 34)" <david.r.payne@dom.com>
Date: March 11, 2016 at 4:09:30 PM EST
To: "Jerry K Miles (Generation - 34)" <Jerry.K.Miles@dom.com>, Scott Quinlan <s.quinlan@gaiconsultants.com>, John Klamut <J.Klamut@gaiconsultants.com>, "Michael A Glagola (Generation - 34)" <michael.a.glagola@dom.com>, "Carter Cole (Generation - 34)" <carter.cole@dom.com>
Cc: "Christine Harris (Generation - 34)" <christine.harris@dom.com>, Reuben Williams <rwilliams@gloverconstruction.com>
Subject: RE: Problem with Flow able fill in S107 needs to be resolved

Jerry,

I agree with adding a vent at the south, the original plug had vents that were not installed. Is there a way to feed pipe in, pump volume and then work back to the North?

Ray

From: Jerry K Miles (Generation - 34)

Sent: Friday, March 11, 2016 3:14 PM

To: Scott Quinlan; John Klamut; Michael A Glagola (Generation - 34); Carter Cole (Generation - 34); David R Payne (Generation - 34)

Cc: Christine Harris (Generation - 34); Reuben Williams

Subject: Problem with Flow able fill in S107 needs to be resolved

Importance: High

Gentlemen,

The flow able fill in S107 Toe Drain is not flowing properly. It is a piling up within 12 feet or so of the entrance and not flowing. I believe there is not enough grade on the pipe for it to flow all the way to the other end. I have called and all stop to the work until we resolve this. In my opinion the only solution is to do as follows. Somehow reinforce the North Bulk Head to handle any back pressure with a steel plate of some strength and add a fitting into the top of it. Drill a vent hole in the top of the pipe on the south end behind the bulkhead, then pump from the north end until the concrete comes up to the top of the vent hole in the South end. In my opinion that is the only way to safely be sure it is full. Please remember I have called a stop to this work and we need to resolve this as soon as possible.

Sincerely,

J. Kevin Miles

Project Manager-Possum Point

Fly Ash Removal

803-983-3344